
































 <b>PERFORMANCE</b> <b>STANDARD</b>						
								
<b>CHEVROLET (.../...)</b>								
<b>HHR</b>								
	01/08 ▶ 06/11		<b>VM4(A) + VM4(A)</b> 574129 + 574129	<b>V45(U) + V45(U)</b> 574112 + 574112		<b>HU45(U) + HU45(U)</b> 578572 + 578572		<b>CAN06(U) + CAN06(U)</b> 583906 + 583906
<b>KALOS</b>								
	03/05 ▶ 06/08		<b>VM107(A) + VM22(A)</b> 574157 + 574147	<b>V55(U) + V41(U)</b> 574118 + 574110	<b>VM44(U)</b> 574196	<b>HU55(U) + HU40(U)</b> 578576 + 578571		<b>CAN10(U) + CAN04(U)</b> 583910 + 583904
<b>LACETTI</b>								
	03/05 ▶		<b>VM107(A) + VM24(A)</b> 574157 + 574149	<b>V55(U) + V48(U)</b> 574118 + 574114	<b>VM4(A)</b> 574129	<b>HU55(U) + HU45(U)</b> 578576 + 578572		<b>CAN10(U) + CAN06(U)</b> 583910 + 583906
<b>MALIBU</b>								
	09/12 ▶ 12/16		<b>VH132(C12) + VH127(C12)</b> 574732 + 574727	<b>V60(A) + V48(U)</b> 574125 + 574114		<b>HU60(U) + HU48(U)</b> 578579 + 578573		<b>CAN11(U) + CAN07(U)</b> 583911 + 583907
<b>MATIZ</b>								
	03/05 ▶ 02/11			<b>V55(U) + V35(A)</b> 574118 + 574107		<b>HU55(U) + HU35(U)</b> 578576 + 578570		<b>CAN10(U) + CAN02(U)</b> 583910 + 583902
<b>NUBIRA</b>								
	03/05 ▶		<b>VM107(A) + VM24(A)</b> 574157 + 574149	<b>V55(U) + V48(U)</b> 574118 + 574114		<b>HU55(U) + HU45(U)</b> 578576 + 578572		<b>CAN10(U) + CAN06(U)</b> 583910 + 583906
<b>SW</b> 	03/05 ▶		<b>VM107(A) + VM24(A)</b> 574157 + 574149	<b>V55(U) + V48(U)</b> 574118 + 574114		<b>HU55(U) + HU45(U)</b> 578576 + 578572		<b>CAN10(U) + CAN06(U)</b> 583910 + 583906
<b>ORLANDO</b>								
	02/11 ▶		<b>VH132(C12) + VH126(C12)</b> 574732 + 574726					
<b>REZZO / TACUMA</b>								
	03/05 ▶		<b>VM16(A) + VM24(A)</b> 574141 + 574149	<b>V60(A) + V48(U)</b> 574125 + 574114	<b>V38(A)</b> 574108	<b>HU60(U) + HU45(U)</b> 578579 + 578572		<b>CAN11(U) + CAN06(U)</b> 583911 + 583906
<b>SILVERADO</b>								
	01/17 ▶					<b>HF55(A) + HF55(A)</b> 578508 + 578508		<b>CAN61(PY) + CAN61(PY)</b> 583961 + 583961
<b>SPARK</b>								
	03/10 ▶ 12/15					<b>HU55(U) + HU35(U)</b> 578576 + 578570		<b>CAN10(U) + CAN02(U)</b> 583910 + 583902
<b>SUBURBAN</b>								
	01/07 ▶ 12/07	<b>VF812</b> 577812				<b>HF55(A) + HF55(A)</b> 578508 + 578508		<b>CAN60(X) + CAN60(X)</b> 583960 + 583960
<b>TAHOE</b>								
	01/07 ▶ 12/07	<b>VF812</b> 577812				<b>HF55(A) + HF55(A)</b> 578508 + 578508		<b>CAN60(X) + CAN60(X)</b> 583960 + 583960
<b>TRAFIC</b>								
	01/97 ▶ 12/02			<b>V51(U) + V51(U)</b> 574116 + 574116		<b>HU50(U) + HU50(U)</b> 578574 + 578574		<b>CAN08(U) + CAN08(U)</b> 583908 + 583908
<b>TRACKER</b>								
<b>2</b> 	01/99 ▶ 02/13			<b>V48(U) + V48(U)</b> 574114 + 574114		<b>HU45(U) + HU45(U)</b> 578572 + 578572		<b>CAN06(U) + CAN06(U)</b> 583906 + 583906
<b>3</b> 	03/13 ▶ 02/21	<b>VF463</b> 574663				<b>HF65(A) + HF35(A)</b> 578513 + 578500		<b>CAN86(PY) + CAN15(PY)</b> 583986 + 583915
<b>TRAX</b>								
	03/13 ▶ 12/21	<b>VF463</b> 574663				<b>HF65(A) + HF35(A)</b> 578513 + 578500		<b>CAN86(PY) + CAN15(PY)</b> 583986 + 583915
<b>VOLT</b>								
	01/11 ▶ 12/19	<b>VF473</b> 574673				<b>HF65(A) + HF65B(A)</b> 578513 + 578514		<b>CAN86(PY) + CAN86(PY)</b> 583986 + 583986
<b>CHRYSLER</b>								
<b>300 M</b>								
	03/98 ▶		<b>VM16(A) + VM11(A)</b> 574141 + 574136	<b>V60(A) + V55(U)</b> 574125 + 574118		<b>HU60(U) + HU55(U)</b> 578579 + 578576		<b>CAN11(U) + CAN10(U)</b> 583911 + 583910
<b>300 C</b>								
	03/04 ▶		<b>VM107(A) + VM11(A)</b> 574157 + 574136	<b>V55(U) + V55(U)</b> 574118 + 574118		<b>HU55(U) + HU55(U)</b> 578576 + 578576		<b>CAN10(U) + CAN10(U)</b> 583910 + 583910
	03/04 ▶		<b>VM107(A) + VM11(A)</b> 574157 + 574136	<b>V55(U) + V55(U)</b> 574118 + 574118		<b>HU55(U) + HU55(U)</b> 578576 + 578576		<b>CAN10(U) + CAN10(U)</b> 583910 + 583910
	03/03 ▶		<b>VM104(A) + VM25(A)</b> 574154 + 574150			<b>HU50(U) + HU53(U)</b> 578574 + 578575		<b>CAN08(U) + CAN09(U)</b> 583908 + 583909